





Sunlight or light from halogen lamps
can disturb the sensor.

Sonnenlicht oder Licht von Halogenlampen
können den Sensor stören.

Skarpt sollys eller halogenlys,
kan forstyrre sensoren.


Starkt solljus eller halogenbelysning
kan störa sensorn.

Directe lichtinval van de zon of van halogeen
lampen kan de sensor storen.


La lumière du soleil ou des lampes à halogène
peut perturber le fonctionnement du détecteur.



Service mode:
Servicemodus:
Servicetilstand: **OFF**
Serviceläge:
Onderhoudsinstelling:
Mode de service:






RS11/1



Recommended height
Empfohlene Höhe
Anbefalet højde
Rekommenderad höjd
Aanbevolen hoogte
Hauteur recommandée

940mm
37"

RS11/2
VR432


RS11/1/2/3

Theft protection
Diebstahlsicherung
Tyverisikring


Stölskydd
Anti diefstal
Antivol







RS11/3



RS11/1 RS11/3




RS11/2



416

23 - 2,5 mm.



2E


426

430


RS11/1

RS11/2/3

419



428



429

420

421

24 - 4 mm.



429

420


432

RS11/2

428



VR410: VR409, VR410
VR426: VR426, 2xVR430
VR431: VR24, VR27, VR423, VR4234, VR425, VR431F, VR431S



vola
Lunavej 2
DK-8700 Horsens
Tlf : + 45 7023 5500
sales@vola.com
www.vola.com

VOLA RS11/1/2/3

Date
Aug. 21

Rev.
1

Sheet
SB 118